
| BT27.35-P-0002-01A | Installation of a pressure feed valve | | |
|---|---|---|---|




P27.35-0212-09

**Production breakpoint data/Modifications/New features**

| *Transmission/ steering gear* | *Transmission ident. end no. as of* | *Type of and reason for modification* |
|---|---|---|
| 722.6 | 0027083 | |

A pressure feed valve (146) has been installed in the 2-3 shift group to prevent harsh 3-2 downshifts and roll-out shifts.